

Hapag-Lloyd India Pvt.Ltd - Container "On Board" Status



Date of issue: 29.07.2016 AT 1748 HRS.

Vessel : YM GREEN

Voyage : v 123E

Port : NHAVA SHEVA

Container Number	Container Type	Port of Discharge
HLXU8590456	4510	COLOMBO
FCIU8630900	4510	COLOMBO
SEGU5650815	4510	SHANGHAI
GESU6513690	4510	SHANGHAI
HLBU1754144	4510	SINGAPORE
CPSU1788836	2210	SHANGHAI
HLBU1642170	4510	SINGAPORE
HLBU1693265	4510	SHANGHAI
UETU5278948	4510	SHANGHAI
TGTU2514317	2270	SHANGHAI
TGTU2514298	2270	SHANGHAI
HLBU1607610	4510	SHANGHAI
TCLU3013632	2210	SHANGHAI
FCIU2908620	2210	HONG KONG
HLXU5232485	4210	SINGAPORE
CLHU4595378	4210	SINGAPORE
TGHU8863788	4510	PORT KELANG

CAIU8218602	4510	COLOMBO
HLBU1238066	2210	PORT KELANG
HLXU6354894	4510	COLOMBO
TRLU5592039	4510	COLOMBO
HLBU1136655	4210	SINGAPORE
HLXU1092718	2210	VUNG TAU
FCIU3730701	2210	HONG KONG
HLXU1146769	2210	PORT KELANG
HLXU1267626	2210	COLOMBO
HLXU3285399	2210	COLOMBO
HLBU1617250	4510	COLOMBO
HLBU1202084	4510	COLOMBO
TRLU7500134	4510	COLOMBO
TCNU6744807	4510	COLOMBO
HLXU8521460	4510	VUNG TAU
HLXU6578385	4510	VUNG TAU
HLXU6282480	4510	VUNG TAU
FSCU6826236	4510	VUNG TAU
CPSU6435657	4510	VUNG TAU
HLXU8002070	4510	VUNG TAU
BSIU9276358	4510	VUNG TAU
HLBU1331878	4510	VUNG TAU
HLXU8452251	4510	VUNG TAU

HLXU6306880	4510	VUNG TAU
DFSU6634053	4510	VUNG TAU
HLXU6279194	4510	VUNG TAU
CPSU6406690	4510	VUNG TAU
CAIU9056532	4510	VUNG TAU
HLXU8196340	4510	VUNG TAU
HLXU8462352	4510	VUNG TAU
HLXU8311314	4510	VUNG TAU
HLXU6315861	4510	VUNG TAU
SEGU5709127	4510	VUNG TAU
HLXU8425929	4510	VUNG TAU
CPSU5167159	4530	SINGAPORE
TRLU3808828	2210	SINGAPORE
CAXU3272048	2210	SINGAPORE
UESU4262080	4210	SINGAPORE
HLXU6490930	4510	COLOMBO
TGHU8772060	4510	PORT KELANG
FCIU2783625	2210	NINGBO
HLXU8413661	4510	SINGAPORE
HLXU8609799	4510	SINGAPORE
HLBU1222820	2210	VUNG TAU
DRYU2015804	2210	SINGAPORE
GESU3645292	2210	SINGAPORE

CLHU3817378	2210	SHANGHAI
FCIU2297963	2210	SHANGHAI
AMFU3271611	2210	SHANGHAI
CAIU2677435	2210	SHANGHAI
TRLU8863263	2210	SHANGHAI
FCIU2547023	2210	PORT KELANG
HLXU8591576	4510	COLOMBO
DRYU2164773	2210	PORT KELANG
INKU6390905	4510	COLOMBO
HLXU1243814	2210	VUNG TAU
HLXU1054282	2210	VUNG TAU
TCLU7297938	2210	VUNG TAU
HLXU1236543	2210	VUNG TAU
FCIU2910890	2210	VUNG TAU
HLXU8375345	4510	COLOMBO
GESU5930426	4510	COLOMBO
GESU6405649	4510	COLOMBO
CPSU6453347	4510	COLOMBO
HLXU8540558	4510	COLOMBO
HLXU6221736	4510	COLOMBO
TGHU3241760	2210	SINGAPORE
CLHU3899930	2210	SINGAPORE
HLBU1764857	4510	SINGAPORE

HLXU8458223	4510	SINGAPORE
HLXU8621182	4510	SINGAPORE
HLXU3201818	2210	NINGBO
HLXU3399637	2210	SHANGHAI
HLBU1014451	4510	COLOMBO
HLXU3071910	2210	HONG KONG
HLXU1405725	2210	COLOMBO
HLXU6219298	4510	COLOMBO
FCIU3428585	2210	COLOMBO
HLBU1759589	4510	SHANGHAI
TCLU5707669	4510	SHANGHAI
HLBU1319888	4510	SHANGHAI
HLXU8022190	4510	COLOMBO
HLBU1605958	4510	SHANGHAI
HLBU1280370	4510	SHANGHAI
SEGU5713744	4510	SHANGHAI
TCLU8081460	4510	SHANGHAI
HLXU1365221	2210	SINGAPORE
HLXU6438418	4510	SHANGHAI
TCLU9503935	4510	SHANGHAI
HLXU6282372	4510	COLOMBO
GLDU5433750	2210	SHANGHAI
TEMU7886350	4510	SHANGHAI

HLBU1316662	4510	SHANGHAI
CAIU9266122	4510	SHANGHAI
HLXU3171499	2210	COLOMBO
FSCU3557175	2210	VUNG TAU
TCLU3197479	2210	SINGAPORE
GLDU3162855	2210	SINGAPORE
FSCU3692241	2210	PORT KELANG
HLBU1010306	4510	SHANGHAI
HLBU1667395	4510	SHANGHAI
HLXU5315126	4210	VUNG TAU
LN XU8458200	4530	COLOMBO
TCLU1177452	4530	COLOMBO
CLHU4531769	4210	COLOMBO
CPSU4033915	4210	COLOMBO
CPSU6456520	4510	COLOMBO
FSCU9658748	4510	COLOMBO
HLBU1195154	4210	COLOMBO
HLBU1493570	4510	COLOMBO
HLXU6244515	4510	COLOMBO
HLXU6338070	4510	COLOMBO
HLXU8167830	4510	COLOMBO
TCLU4476987	4210	COLOMBO
TGHU6228079	4510	COLOMBO

TTNU5919101	4210	COLOMBO
HLXU8241860	4510	SHANGHAI
CAIU8078938	4510	COLOMBO
GATU8582355	4510	COLOMBO
BSIU2299156	2210	SHANGHAI
HLXU8058633	4510	COLOMBO
HLXU8573910	4510	COLOMBO
IPXU3526703	2210	SHANGHAI
FCIU8736087	4510	COLOMBO
TRLU7388940	4510	COLOMBO
DFSU6608537	4510	COLOMBO
GESU6561976	4510	COLOMBO
HLXU1135872	2210	SHANGHAI
HLXU8101719	4510	SHANGHAI
TCLU5708897	4510	COLOMBO
TGHU9447830	4510	COLOMBO
TCNU9130490	4510	COLOMBO
CAIU4061480	4210	SHANGHAI
GESU3909369	2210	SHANGHAI
HLXU6285670	4510	SHANGHAI
HLXU5260002	4210	VUNG TAU
HLXU6523401	4510	COLOMBO
BMOU4042710	4510	HONG KONG

BEAU2203004	2210	HONG KONG
HLXU8090656	4510	HONG KONG
CPSU1713586	2210	SINGAPORE
TRLU8849049	2210	SINGAPORE
TCLU2814149	2210	SINGAPORE
CRLU7211602	4530	SINGAPORE
HLXU3733507	2230	SINGAPORE
HLXU3701475	2230	SINGAPORE
HLXU3718971	2230	SINGAPORE
BSIU2254064	2210	PORT KELANG
HLXU3459612	2210	PORT KELANG
FCIU4456724	2210	PORT KELANG
HLXU3511182	2210	PORT KELANG
GLDU3995717	2210	PORT KELANG
HLXU1252800	2210	PORT KELANG
GLDU7591478	4510	COLOMBO
GESU4581037	4510	SINGAPORE
GESU3626918	2210	SINGAPORE
IRNU5513761	4510	SHANGHAI
TCLU2648650	2210	SHANGHAI
HLBU1767917	4510	SINGAPORE
HLXU5107550	4210	SINGAPORE
FCIU8341180	4510	PORT KELANG

TRLU4800420	4210	SHANGHAI
TGHU4990573	4210	SHANGHAI
FCIU2107338	2210	VUNG TAU
TGHU7993658	4510	VUNG TAU
HLXU1001596	2210	HONG KONG
HLBU1009291	2210	HONG KONG
FCIU8074057	4510	COLOMBO
CLHU8399434	4510	COLOMBO
HLXU6548903	4510	COLOMBO
HLXU3184623	2210	SINGAPORE
BEAU2200535	2210	SINGAPORE
HLXU6530566	4510	SINGAPORE
TGHU2230993	2210	SINGAPORE
CRXU8614425	2270	SHANGHAI