

SAFETY MANAGEMENT CERTIFICATE

DNV·GL

Certificate No:
SMC-998173-1
DNV GL Id No:
G130181
Date of issue:
2017-05-31

Issued under the provisions of the INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA,
1974, as amended
under the authority of the Government of

THE REPUBLIC OF LIBERIA

by **DNV GL**

Particulars of Ship

Name of Ship:	SANTA VANESSA
Distinctive Number or Letters:	91116
Port of Registry:	MONROVIA
Type of Ship ¹ :	Other cargo ship
Gross Tonnage:	65483
IMO Number:	9295361

Particulars of Company²

Company Name:	CPO Containerschiffreederei (GmbH & Co.) KG
Company Address:	Bleichenbrücke 10 20354 Hamburg GERMANY
Company Identification Number:	5849027

This is to certify:

that the safety management system of the ship has been audited and that it complies with the requirements of the International Management Code for the Safe Operation of Ships and for Pollution Prevention (ISM Code), following verification that the Document of Compliance for the Company is applicable to this type of ship.

This Safety Management Certificate is valid until **2020-11-02**, subject to periodical verification and the validity of the Document of Compliance remaining valid.

Completion date of audit on which this Certificate is based: **2015-09-21**

Issued at **Antwerpen , Belgium** on **2017-05-31**

for **DNV GL**


Grzegorz Włodarczyk
Surveyor



¹ Insert the standard IMO ship type.

² See paragraph 1.1.2 of the ISM Code.



Form code: 40.098a

n998173-1-gvb

Revision: 2016-11

www.dnvgl.com

Page 1 of 3

Certificate No: **SMC-998173-1**
Date of issue: **2017-05-31**

Endorsement for periodical verification and additional verification (If required)

THIS IS TO CERTIFY:

that at the periodical verification in accordance with regulation IX/6.1 of the Convention and paragraph 13.8 of the ISM Code, the safety management system was found to comply with the requirements of the ISM Code.

Intermediate Verification³: Place: _____ Date: _____

Stamp _____ Signature: _____
Surveyor, DNV GL

Additional Verification⁴: Place: **Valencia, Spain** Date: **2016-06-10**

Stamp  Signature: 
Surveyor, DNV GL

Additional Verification⁴: Place: _____ Date: _____

Stamp _____ Signature: _____
Surveyor, DNV GL

Additional Verification⁴: Place: _____ Date: _____

Stamp _____ Signature: _____
Surveyor, DNV GL

³ To be completed between the second and third anniversary dates.

⁴ If applicable. Reference is made to the relevant provisions of section 4.3 "Initial Verification" of the Revised Guidelines on Implementation of the International Safety Management (ISM) Code by Administrations adopted by the Organization by resolution A.1071(28).

Certificate No: **SMC-998173-1**
Date of issue: **2017-05-31**

Endorsement where the renewal verification has been completed and part B 13.13 of the ISM Code applies

The ship complies with the relevant provisions of part B of the ISM Code, and the Certificate should, in accordance with part B 13.13 of the ISM Code, be accepted as valid until:

Place: _____ Date: _____

Signature: _____

Stamp

Surveyor, DNV GL

Endorsement to extend the validity of the Certificate until reaching the port of verification where part B 13.12 of the ISM code applies or for a period of grace where part B 13.14 of the ISM code applies

This Certificate should, in accordance with part B 13.12 or part B 13.14 of the ISM Code, be accepted as valid until:

Place: _____ Date: _____

Signature: _____

Stamp

Surveyor, DNV GL